



# Volkswagen Passat

VIN NUMBER  
1VWBN7A35CCXXXXX

**DATA SCIENCE APPLIED** while generating this report


Reports are additionally spot-checked by our data scientists to ensure their quality.

**NMVTIS approved data partner**


This report has been prepared in cooperation with the National Motor Vehicle Title Information System.

**BLOCKCHAIN-VERIFIED** and authentic


This report has been saved on blockchain to ensure authenticity and prevent tampering.



Scroll for more



## NMVTIS Vehicle History



An NMVTIS Vehicle History Report is intended to provide data on state of title, odometer reading, brand, total loss and salvage history

### Title Records 3 records found!

This section lists title records.

TITLE ISSUE DATE	STATE OF TITLE	MILEAGE	TYPE	VIN
2016-02-20	New York	59,800 mi	current	1VWBN7A35CCXXXXX
2015-01-15	New Jersey	51,600 mi	historical	1VWBN7A35CCXXXXX
2014-01-23	Pennsylvania	40,800 mi	historical	1VWBN7A35CCXXXXX

### Junk / Salvage / Insurance Records 2 records found!

This section lists junk, salvage, and insurance records (if any).

VEHICLE OBTAINED DATE	ENTITY	DETAILS	EXP	VIN
2015-01-01	Intertrade Inc., Bridgeview, IL	Junk and Salvage / Vehicle state: sold	No	1VWBN7A35CCXXXXX
2014-06-01	IA, Awestchester, IL	Junk and Salvage / Vehicle state: sold	No	1VWBN7A35CCXXXXX

### Mileage 8 records found!

This section lists our checks for potential problems related to the odometer.

Odometer: Actual? 🔍 ✔️ No problems found!

Odometer: Not Actual? 🔍 ✔️ No problems found!

Odometer: Tampering Verified? 🔍 ✔️ No problems found!

Odometer: Exempt from Odometer Disclosure? 🔍 ✔️ No problems found!

Show more

### Title Checks 1/21 bad records found!

This section lists our checks for potential problems related to the title.

Record of Prior Police? 🔍 ✔️ No problems found!

Record of Gray Market Compliant? 🔍 ✔️ No problems found!

Record of Owner Retained? 🔍 ✔️ No problems found!

Record of Flood Damage? 🔍 ✔️ No problems found!

Show more

#### NMVTIS Disclaimer

The National Motor Vehicle Title Information System (NMVTIS) is an electronic system that contains information on certain automobiles titled in the United States. NMVTIS is intended to serve as a reliable source of title and brand history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.

All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMVTIS. However, NMVTIS does not contain information on all motor vehicles in the United States because some states are not yet providing their vehicle data to the system. Currently, the data provided to NMVTIS by states is provided in a variety of time frames; while some states report and update NMVTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling state has not determined the vehicle to be "salvage" or "junk". Before making a decision to purchase a vehicle, consumers may wish to obtain an independent vehicle inspection, a NMVTIS Vehicle History Report, and consult other available vehicle information resources.

The information in NMVTIS includes:

Information from participating state motor vehicle titling agencies.

Information on automobiles, buses, trucks, motorcycles, recreational vehicles, motor homes, and tractors. NMVTIS may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, these vehicles are managed by a separate state agency), although these records may be added at a later time.

Information on "brands" applied to vehicles provided by participating state motor vehicle titling agencies. Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.

Most recent odometer reading in the state's title record.


Information from insurance companies, and auto recyclers, including junk and salvage yards, that is required by law to be reported to the system, beginning March 31, 2009. This information will include if the vehicle was determined to be a "total loss" by an insurance carrier.

Information from junk and salvage yards receiving a "cash for clunker" vehicle traded-in under the Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.

Consumers are advised to visit [www.vehiclehistory.gov](http://www.vehiclehistory.gov) for details on how to interpret the information in the system and understand the meaning of various labels applied to vehicles by the participating state motor vehicle titling agencies.

#### carVertical Disclaimer

The information used to compile this report is aggregated from various government agencies, non-profit organizations and industry sources. Access to the National Motor Vehicle Title Information System (NMVTIS) is facilitated through Approved NMVTIS Consumer Access Provider carVertical. Nonetheless, the accuracy and reliability of the information supplied depends primarily on the reporting sources, and all entities involved in compiling this report accept no liability for any errors or omissions. Furthermore, all warranties, expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose, are hereby disclaimed.




## Photos

Based on archive searches, this vehicle was spotted in the following photos. Pay close attention to possible body damage, as well as colour and exterior elements. Compare it to what you see now.

UPLOADED

2017-04-20



## Damage

- 2018-03 **Damage record**
- 2014-02 **Damage record**
- 2014-02 **Damage record**

**Front right / Bumper**

DAMAGE HAPPENED IN **France** | DAMAGE AMOUNT **17 000 €** | POSSIBLE DAMAGE TYPE **Unknown**

### Title Checks 1/32 bad records found!

This section lists our checks for potential problems related to the title.

Record of Salvage Damage or Not Specified? 🔍 ⚠️ Records found!  
Date: 2016-01-01T12:00:0Z  
Brander: New York (state)  
Date: 2016-01-01T12:00:0Z  
Brander: AA

Record of No Brand for the Vehicle? 🔍 ✔️ No problems found!


Record of Flood Damage? 🔍 ✔️ No problems found!

Record of Fire Damage? 🔍 ✔️ No problems found!

Record of Hail Damage? 🔍 ✔️ No problems found!

Record of Salt Water Damage? 🔍 ✔️ No problems found!

Show more



## Spotted Activity

Wonder what countries this vehicle has been registered in? Check our radar. Compare it with what the trader says.

- 2014-01-07 **Was on sale, US**
- 2014-02-03 **Was on sale, US**
- 2017-02-01 **Was inspected, US**
- 2017-11-24 **Was on sale, Canada**



**CARVERTICAL ADVICE**

Please check if that corresponds with actual documents, e.g. records in service book.




## Equipment

The list below represents the equipment options that were installed in the factory. Go ahead and check if anything is missing.

CODE	DESCRIPTION	CODE	DESCRIPTION
E0A	Special editions No special editions	1PA	Lockable wheel bolts Standard wheel bolts
ODI	Vehicle class differentiation units/platform components Vehicle class differentiation -360-	7MG	Emissions standard Emission standard EU5
1D0	Trailer hitch Without trailer hitch	4UE	Airbag Air bag for driver and front seat passenger
1E1	Activated carbon canister Activated carbon canister	8ZH	Antennas Antenna for AM/FM reception, "diversity"
6XU	Exterior mirrors automatically dimming, electrically adjustable, separately heated	EA0	Follow-on warranty Without subsequent warranty
5SL	Left exterior mirror aspherical	5RQ	Right exterior mirror convex
1X0	Drive layout Front wheel drive	9WL	"Multimedia", video/DVD/notebook connection Multimedia socket for external audio source
A8B	Equipment levels Basic equipment	1KW	Brake type in rear Disc brakes, rear
J0L	Batteries Battery 340 A (70 Ah)	1ZM	Brake type, front Disc brakes, front / Geomet D)

Show more




## VIN Location

It's important to double-check that all VIN numbers on the vehicle match. Usually the manufacturer places the VIN in 1-3 locations.



At the bottom corner of a windshield, driver side



Under the engine hood, next to the lock



On the right side of a spare wheel (in the trunk)



## Pay Attention To

Almost every model has its own specific cons. Be aware if this is the case with the vehicle of your interest.

- Common EGR failure on TDI engines**
- Failed A/C compressor**
- Manual transmission failure**
- TDI engine suffers from EGR valve failure after the VAG Nox emissions fix**
- Very common dual mass flywheel failure additionally resulting in clutch and transmission failures**